



SPEEDY PLUS



SPEEDY SUPER

Dimensioni macchina Machine dimensions Dimensiones máquina Dimensions de la machine Maschinenabmessungen	100 x 160 x 370h mm	150 x 240 x 380h mm
Peso   Weight   Peso   Poids   Gewicht	1,26 kg	4 kg
Voltaggio   Voltage   Voltaje   Tension   Spannung	120 V-60 Hz ● 230 V-50/60 Hz	110 V-50/60 Hz-1ph ● 230 V-50/60 Hz-1ph
Consumo   Consumption   Consumo   Consommation   Leistung	1200 W	1650 W / 2000 W
Quantità tutolo   Mais powder amount   Cantidad de polvo de maíz   Quantité de granulé de maïs   Maisgranulat-Menge	3 kg	5 kg
Supporto per posate   Cutlery basket holder   Soporte para cubiertos   Support pour couvert   Besteckträger	●	●
Posate per ora   Cutlery per hour   Cubiertos por hora   Couverts par heure   Bestecke pro Stunde	3000	6000

### SPEEDY GLASS

Dimensioni macchina Machine dimensions Dimensiones máquina Dimensions de la machine Maschinenabmessungen	325 x 300 x 500 h mm
Peso   Weight   Peso   Poids   Gewicht	15,5 kg
Voltaggio   Voltage   Voltaje   Tension   Spannung	220-240 V-50/60 Hz
Consumo   Consumption   Consumo   Consommation   Leistung	1,15-1,35 kW
Getto d'aria   Air flow   Chorro de aire   Jet d'air   Luftstrahl	164 CFM
Temperatura aria calda   Hot air temperature   Temperatura aire caliente   Température de l'air chaud   Temperatur der warmen Luft	55-60 °C
Bicchieri per ora   Glasses per hour   Vasos por hora   Verres pour heure   Gläser per Stunde	350

